



Material Safety Data Sheet

Trade Name: HVMT Copper

Date Prepared: November 12, 2009

Prepared by: Peter Haug

Section 5: Health Hazard Data

Primary Route of Entry:	<u>N/A</u> Inhalation	<u>N/A</u> Skin Absorption
	<u>N/A</u> Ingestion	<u>N/A</u> Not Hazardous
Carcinogen Listed In:	<u>N/A</u> NTP	<u>N/A</u> IRAC Monograph
	<u>N/A</u> OSHA	<u>N/A</u> Not Listed
Health Hazards:	Acute: <u>N/A</u>	
	Chronic: <u>N/A</u>	
Signs & Symptoms of Exposure:	<u>N/A</u>	
Medical Conditions Aggravated by Exposure:	None Known	
Emergency First Aid Procedures:	Seek Medical Advice	
Eye Contact:	<u>N/A</u>	
Skin Contact:	<u>N/A</u>	
Inhalation:	<u>N/A</u>	
Ingestion:	Not expected route of entry	

Section 6: Control & Protective Measures

Respiratory Protection:	Dust mask if required		
Protective Gloves:	<u>N/A</u>		
Eye Protection:	<u>N/A</u>		
Ventilation to be Used:	<u>N/A</u> Local Exhaust	<u>N/A</u> Mechanical (General)	<u>N/A</u> Special
	Other (Specify) <u>N/A</u>		
Other Protective Clothing or Equipment:	<u>N/A</u>		
Hygienic Work Practices:	<u>N/A</u>		

Section 7: Precautions for Safe Handling and Use / Leak Procedures

Steps Taken if Material Spilled or Released:	<u>N/A</u>
Waste Disposal Methods:	In accordance with Federal, Provincial and local laws
Precautions Taken in Handling & Storage:	Store and handle using good warehouse practices Avoid excess temperature and humidity
Other Precautions and/or Special Hazards:	<u>N/A</u>